

ASSOCIATION OF AMERICAN RAILROADS—RECORD REPAIR CARD
 WISCONSIN STEEL COMPANY, Incorporated
(TO BE RETAINED BY PARTY
MAKING REPAIRS)

END	REPAIRS MADE	Net Price	LABOR		Wrot. Iron	Mall. Iron	Lumber	Springs	WHY MADE
			Hours						
A&B.	4-Hopper Door Channels straightened, R.R. & R. 1607	3.36							A/C. Bent-Unable straighten on car.
A&B.	84-5/8" Hopper Door Channel rivets renewed.	21.38							A/C. Repairs.
BR.	1-Hopper Door straightened, R.R. & R. 859	1.79							A/C. Bent-Unable straighten on car.
BR.	8-5/8" Hopper Door rivets renewed.	2.00							A/C. Repairs.
BR.	1-Slope Floor angle straightened, R.R. & R. 549	1.13							A/C. Bent-Unable straighten on car.
BR.	17-5/8" Slope Floor angle rivets renewed.	4.25							A/C. Repairs.
BR.	1-Slope Floor sheet straightened, Repaired on car.		5	.0					A/C. Bent.
BR.	1-Inside Hopper sheet straightened, Repaired on car.		1	.0					A/C. Bent.
	Authy-L&N. defect card issued at Loyall, Ky., 12-1-39 by R.B. Street.								
		33.91	6	.0					

Date 12-7- 39 Repaired at Benham, Ky. Inspector D.L. Kunnery
 Car No. 306 Initial or Name WBNX. Kind Hopper